

Ship Name: **BAHAMA PRIDE**  
IMO Number: **7717717**  
Date Detained: **02/17/2002**

Ship Type: **General Dry Cargo Ship**  
Flag: **Panama**  
Class Society: **Panama Maritime Documentation Service**

Port: **Miami, Florida**

Company(s): Owners, Operators or  
**G & G Marine, Inc**

Deficiencies: Code - Category  
**1299 - Other (Load Lines)**

Description  
**#1 starboard ballast tank holed in forward engineering tunnel, behind shelving.**

**1299 - Other (Load Lines)**

**#3 starboard ballast tank holed at frame #25 above piping.**

**1299 - Other (Load Lines)**

**Piping and wiring penetrations going through the forward and aft bulkheads of engine room by watertight doors are not watertight.**

**1270 - Doors**

**Watertight doors in forward port side out of engine room and aft watertight door not able to be properly secured.**

**1299 - Other (Load Lines)**

**The portside ballast manifold piping in engine room has soft patches located in the bilge.**

**1299 - Other (Load Lines)**

**Ballast tank #8 port and starboard side in steering space is holed with ballast water coming into steering space.**

**1299 - Other (Load Lines)**

**Ballast water flowing from the #7 starboard ballast tank into the #6 starboard ballast tank.**

**1299 - Other (Load Lines)**

**The manhole cover inside the chain locker leading to the forward peak is missing.**

**1299 - Other (Load Lines)**

**Several gussets in way of the stem of the bow are wasted.**

**1299 - Other (Load Lines)**

**Wasted framing in the #1 port ballast tank.**

~~~~~  
Ship Name: **BLUE HAWK**  
IMO Number: **7800370**  
Date Detained: **02/01/2002**  
Port: **Jacksonville, Florida**

Ship Type: **Ro-Ro-Cargo Ship**  
Flag: **Liberia**  
Class Society: **Nippon Kaiji Kyokai**  
Company(s): Owners, Operators or  
**Tanda Marine Co. LTD**  
**Gratitude Maritime Company Ltd.**

Deficiencies: Code - Category  
**0610 - Lifeboats**

Description  
**Unable to lower port and starboard lifeboats due to inoperative davits.**

|                |                            |                |                                                                                |
|----------------|----------------------------|----------------|--------------------------------------------------------------------------------|
| Ship Name:     | <b>DOCEALFA</b>            | Ship Type:     | <b>Bulk Carrier</b>                                                            |
| IMO Number:    | <b>7526558</b>             | Flag:          | <b>Liberia</b>                                                                 |
| Date Detained: | <b>02/28/2002</b>          | Class Society: | <b>American Bureau of Shipping</b>                                             |
| Port:          | <b>Baltimore, Maryland</b> | Company(s):    | <u>Owners, Operators or</u><br><b>Navegacao Vale Do Rio Doce S.A. Docenave</b> |

| Deficiencies: | <u>Code - Category</u>                            | <u>Description</u>                                                                       |
|---------------|---------------------------------------------------|------------------------------------------------------------------------------------------|
|               | <b>0936 - Steering gear</b>                       | <b>Steering gear system and indicator</b>                                                |
|               | <b>0950 - Electric equipment in</b>               | <b>Sea water piping for freshwater cooling on generator leaking on electrical panel.</b> |
|               | <b>0720 - Fire fighting equipment</b>             | <b>Soft patch on main fire pump No.2.</b>                                                |
|               | <b>0999 - Other (Safety In General)</b>           | <b>Excessive cooling water leaking from SSDG's 1 &amp; 3.</b>                            |
|               | <b>0945 - Emergency lighting, etc</b>             | <b>Emergency generator would not start on batteries.</b>                                 |
|               | <b>0680 - Embarkation arrangt. survival craft</b> | <b>Davit support framing on stbd lifeboat davits wasted</b>                              |
|               | <b>0680 - Embarkation arrangt. survival craft</b> | <b>Fwd/ Aft lifting hook bases wasted inside stbd lifeboat.</b>                          |
|               | <b>0680 - Embarkation arrangt. survival craft</b> | <b>Port lifeboat hull fractured /holed on stbd side fwd.</b>                             |
|               | <b>0680 - Embarkation arrangt. survival craft</b> | <b>Port lifeboat grab rail on starboard lifeboat wasted/missing.</b>                     |
|               | <b>2020 - Fire drills</b>                         | <b>Crew unable to demonstrate proficiency for fire drill.</b>                            |

~~~~~

Ship Name:	<b>GENMAR MACEDON</b>	Ship Type:	<b>Tankship (Not Specified)</b>
IMO Number:	<b>8819146</b>	Flag:	<b>Marshall Islands</b>
Date Detained:	<b>02/23/2002</b>	Class Society:	<b>American Bureau of Shipping</b>
Port:	<b>St. Croix, USVI</b>	Company(s):	<u>Owners, Operators or</u> <b>United Tankers Limited</b>

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	<b>0150 - Oil pollution prevention (IOPP)</b>	<b>Overboard discharge line for Oil Discharge Monitoring Equipment (ODME) is compromised allowing the discharge of oil into the water.</b>

Ship Name: **GRAND PANAYOTIS** Ship Type: **Bulk Carrier**  
IMO Number: **7923940** Flag: **Saint Vincent and the Grenadines**  
Date Detained: **02/02/2002** Class Society: **American Bureau of Shipping**  
Port: **New Orleans, Louisiana** Company(s): Owners, Operators or  
**Overseas Marine Enterprises, Inc.**

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	<b>1499 - Other (Prop. &amp; Aux. Machinery)</b>	<b>No. 2 generator leaking fuel from the main fuel pump.</b>
	<b>1499 - Other (Prop. &amp; Aux. Machinery)</b>	<b>No. 3 generator has excessive fuel leaking from No. 1, 2, 4,5 , &amp; 6 high injector lines.</b>
	<b>1499 - Other (Prop. &amp; Aux. Machinery)</b>	<b>No. 3 generator has major air leak on inlet air manifold.</b>

~~~~~

Ship Name: **JEANNY CAY** Ship Type: **General Dry Cargo Ship**  
IMO Number: **7501584** Flag: **Honduras**  
Date Detained: **02/19/2002** Class Society: **Honduras International Naval Surveying and Inspection Bureau**  
Port: **Miami, Florida** Company(s): Owners, Operators or  
**Schurger Diving & Salvage Inc.**

| Deficiencies: | <u>Code - Category</u>                     | <u>Description</u>                                                            |
|---------------|--------------------------------------------|-------------------------------------------------------------------------------|
|               | <b>0610 - Lifeboats</b>                    | <b>Port and starboard life rafts are overdue for servicing .</b>              |
|               | <b>0625 - Rigid liferafts</b>              | <b>Hydrostatic release units for both liferafts expired.</b>                  |
|               | <b>0615 - Rescue boats</b>                 | <b>Rescue boat winch is inoperable.</b>                                       |
|               | <b>0720 - Fire fighting equipment</b>      | <b>Fire main is wasted and holed.</b>                                         |
|               | <b>0230 - Number/composition (manning)</b> | <b>Vessel is not properly manned in accordance with safe manning document</b> |

|                |                              |                |                                                            |
|----------------|------------------------------|----------------|------------------------------------------------------------|
| Ship Name:     | <b>MANINHA</b>               | Ship Type:     | <b>General Dry Cargo Ship</b>                              |
| IMO Number:    | <b>7041508</b>               | Flag:          | <b>Cape Verde</b>                                          |
| Date Detained: | <b>02/23/2002</b>            | Class Society: | <b>Govt of Listed Flag</b>                                 |
| Port:          | <b>Newport, Rhode Island</b> | Company(s):    | <u>Owners, Operators or</u><br><b>Draga Verde Limitada</b> |

| Deficiencies: | <u>Code - Category</u>                          | <u>Description</u>                                                                                                                                                                                                                            |
|---------------|-------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|               | <b>0720 - Fire fighting equipment</b>           | <b>Fire main wasted and holed. No fire hydrants above the main deck in the deck house were operational. One of two hydrants in the engine room was operational.</b>                                                                           |
|               | <b>0730 - Appliances (general equipment)</b>    | <b>No fixed fire extinguishing system installed in the engine room.</b>                                                                                                                                                                       |
|               | <b>0696 - Record of inspections/maintenance</b> | <b>Inflatable liferaft not serviced annually. Last serviced in 1999, one of two case closing bands was missing.</b>                                                                                                                           |
|               | <b>0672 - EPIRB's for survival craft</b>        | <b>EPIRB batteries expired.</b>                                                                                                                                                                                                               |
|               | <b>0699 - Other (Life Saving Appliances)</b>    | <b>SART batteries expired.</b>                                                                                                                                                                                                                |
|               | <b>0696 - Record of inspections/maintenance</b> | <b>Two ring buoys not in serviceable condition.</b>                                                                                                                                                                                           |
|               | <b>0611 - Lifeboat inventory</b>                | <b>Port and Starboard lifeboats missing oar locks, sails, &amp; boat plugs.</b>                                                                                                                                                               |
|               | <b>0696 - Record of inspections/maintenance</b> | <b>Lifeboat falls &amp; sheaves not in proper working order. Missing bolt port lifeboat davit. Port lifeboat getting caught on cradle during lowering. No documentation onboard regarding the changeout or end for end of lifeboat falls.</b> |
|               | <b>0696 - Record of inspections/maintenance</b> | <b>Starboard lifeboat hull has hole in vicinity of keel.</b>                                                                                                                                                                                  |
|               | <b>0663 - Immersion suits</b>                   | <b>Crew unable to provide sufficient number of immersion suits and/or thermal protective aids..</b>                                                                                                                                           |
|               | <b>0660 - Lifejackets</b>                       | <b>Crew unable to provide adequate number of lifejackets for crew onboard and at watchstations.</b>                                                                                                                                           |
|               | <b>1570 - Nautical publications</b>             | <b>Navigation publications outdated and not currently corrected.</b>                                                                                                                                                                          |
|               | <b>0936 - Steering gear</b>                     | <b>No steering gear tests or drills conducted or logged.</b>                                                                                                                                                                                  |

Ship Name: **MOL INDEPENDENCE**  
IMO Number: **8608585**  
Date Detained: **02/17/2002**  
Port: **Charleston, South Carolina**

Ship Type: **Bulk Carrier**  
Flag: **Panama**  
Class Society: **Nippon Kaiji Kyokai**  
Company(s): Owners, Operators or  
**Karakoram Maritima S. A.**  
**Mitsui O.S.K. Lines Ltd.**

Deficiencies: Code - Category  
**1730 - Oily-water separating  
equipment**

Description  
**Inoperable Oily Water Separator.**

~~~~~  
Ship Name: **TRANSFER**  
IMO Number: **7124910**  
Date Detained: **02/14/2002**  
Port: **Tampa, Florida**

Ship Type: **General Dry Cargo Ship**  
Flag: **Cayman Islands**  
Class Society: **Germanischer Lloyd**  
Company(s): Owners, Operators or  
**Southwest Transfer Ltd.**  
**Morton & Co**

Deficiencies: Code - Category  
**0740 - Pumps**

Description  
**Fire pump inoperable.**

~~~~~  
Ship Name: **TROPIC PALM**  
IMO Number: **7625964**  
Date Detained: **02/21/2002**  
Port: **St. Thomas, USVI**

Ship Type: **General Dry Cargo Ship**  
Flag: **Saint Vincent and the Grenadines**  
Class Society: **Bureau Veritas**  
Company(s): Owners, Operators or  
**Tropical Shipping & Construction Co. Ltd.**

Deficiencies: Code - Category  
**0740 - Pumps**

Description  
**Inoperable emergency fire pump.**

Ship Name: **VIKINGFJORD**  
IMO Number: **7526699**  
Date Detained: **02/15/2002**  
Port: **Houston, Texas**

Ship Type: **Bulk Carrier**  
Flag: **Norway**  
Class Society: **Det Norske Veritas**  
Company(s): Owners, Operators or  
**Myklebust Haug Rederi AVS**

| <u>Code - Category</u>                          | <u>Description</u>                                                                                                                                    |
|-------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>0720 - Fire fighting equipment</b>           | <b>Main and emergency fire pumps could not provide adequate pressure.</b>                                                                             |
| <b>0610 - Lifeboats</b>                         | <b>No motor lifeboat onboard.</b>                                                                                                                     |
| <b>0745 - Fire-dampers remote control, etc.</b> | <b>Multiple fire dampers throughout ship found inoperable.</b>                                                                                        |
| <b>1299 - Other (Load Lines)</b>                | <b>Steel plating of port and starboard stack structures wasted and holed.</b>                                                                         |
| <b>0611 - Lifeboat inventory</b>                | <b>Rations in both port and starboard lifeboats not stowed in watertight containers.</b>                                                              |
| <b>0610 - Lifeboats</b>                         | <b>No thermal protective aids in both port and starboard lifeboats.</b>                                                                               |
| <b>0899 - Other (accid. prevent.)</b>           | <b>Leaking soft patch on sewage piping at overboard discharge valve</b>                                                                               |
| <b>0745 - Fire-dampers remote control, etc.</b> | <b>Vent closures missing on port and starboard stack structures.</b>                                                                                  |
| <b>0699 - Other (Life Saving Appliances)</b>    | <b>Port and starboard oil transfer containments are corroded and missing plugs.</b>                                                                   |
| <b>0930 - Stability/strength</b>                | <b>Trim and stability booklet is not approved.</b>                                                                                                    |
| <b>1230 - Railing cat walks</b>                 | <b>Numerous guard rails on port and starboard sides are missing or wasted and deck plating or cat walk leading to forecastle ladder found wasted.</b> |